


Book 3




McCAULEY

PROPELLER LOGBOOK


Printed in U.S.A.
February 1988

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signature Repairman and Station Certificate Numbers
5-4-07		856.2	re-installed propeller	
		TACH.	After overhaul, verified	
			DYN. Bal. at .07 IPS.	
			using Aces 2020 pro-Balaner	AMP 142580607
				


NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 1

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
11/1/07	TACH:	907:08	Removed propeller,	PO - 148-8
			re-installed after engine overhaul, prop. inst.	
			ITAW A 100 hr insp. and Found in airworthy cond.	ATP 148580607
			at this time.	

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
9-26-08	08		<p>I certify that I have insp. This propeller I/A/W a 100 hr. insp. as per McCauley maint inst. and found it to be in airworthy cond. visually insp. Hub + blades, no defects noted, replaced spinner Dome Fwd. Bulkhead.</p>	<p>AWP149JEO607</p> 


NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY


Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
			<p>9-18-09 Tack time 1087.24hrs TSP04</p> <p>231 hrs Completed Annual Insp.</p> <p>T.A. With the manufacturers</p> <p>maintenance manual & found</p> <p>airworthy Jim Tingfield I/A 383483256</p>	


NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12


MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work			Authorized Signatures Repairman and Station Certificate Numbers
FINEFIELD AVIATION						
PROPELLER LOG					DATE: 9-18-09	
A/C N#	MAKE	MODEL	A/C S/N	HM	TSPOH	
5746K	Beech	S35	D-7533	1087.21	231	
Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades. Shimmed front spinner bulkheads as necessary.						
<p>This aircraft has been found airworthy for return to service with respect to the work described herein.</p> <p>Authorized Signature:  Printed Name: James Finefield AP 353483286 IA For Finefield Aviation, 8407 Pyott Road, Lake in the Hills, IL 60156 Phone:</p>						
NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12						

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work			Authorized Signature
Repairman and Station Certificate Number						
FINEFIELD AVIATION						
PROPELLER LOG					DATE: 9-24-10	
A/C N#	MAKE	MODEL	A/C S/N	HM	TSPOH	
5746K	Beech	S35	D-7533	1204.96	348.5	
Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades.						
<p style="text-align: center;">This aircraft has been found airworthy for return to service with respect to the work described herein.</p> <p>Authorized Signature:  Printed Name: James Finefield AP 353483286 IA For Finefield Aviation, 2399 Pvott Road, Lake in the Hills, IL 60156 Phone: 815-459-4858</p>						
<p>NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12</p>						

FINEFIELD AVIATION						
PROPELLER LOG					DATE: 9-9-11	
A/C N#	MAKE	MODEL	A/C S/N	HM	TSPOH	
5746K	Beech	S35	D-7533	1297.4	441.2	
Inspected prop I.A.W. an annual inspection and found to be in airworthy condition. Dressed prop blades. Painted propeller faces flat black.						
This aircraft has been found airworthy for return to service with respect to the work described herein. Authorized Signature:  Printed Name: James Finefield AP 353483286 IA For Finefield Aviation.. 8399 Pyott Road, Lake in the Hills, IL 60156 Phone: 815-459-4858						


FINEFIELD AVIATION						
PROPELLER LOG					DATE: 9-21-12	
A/C N#	MAKE	MODEL	A/C S/N	HM	TSPOH	
5746K	Beech	S35	D-7533	1390	533.8	
Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades.						
This aircraft has been found airworthy for return to service with respect to the work described herein. Authorized Signature:  Printed Name: James Finefield AP 353483286 IA For Finefield Aviation.. 8399 Pyott Road, Lake in the Hills, IL 60156 Phone: 815-459-4858						

Y

ures
tion
ers

12

F.A.A. AIRWORTHINESS DIRECTIVE AND SERVICE BULLETIN/ LETTER COMPLIANCE RECORD

Date	Total Propeller Time	Time Since Overhaul	A.D./Bulletin/Letter Number			Authorized Signatures Repairman and Station Certificate Numbers
FINEFIELD AVIATION						
PROPELLER LOG					DATE: 10-13-14	
A/C N#	MAKE	MODEL	A/C S/N	HM	TSPOH	
5746K	Beech	S35	D-7533	1567.9	711.7	
Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades.						
This aircraft has been found airworthy for return to service with respect to the work described herein.						
Authorized Signature:  Printed Name: James Finefield AP 353483286 IA						
For Finefield Aviation, 8399 Pyott Road, Lake in the Hills, IL 60156 Phone: 815-459-4858						